



PROJECT PROFILE

PROJECT: Waste Water Treatment Plant
LOCATION: Latvia

THE PROBLEM

The external surfaces of the metal valves and waste water outlets had gradually deteriorated over a period of time.

Rust was now showing through extensively and they were therefore in need of a complete upgrade to prevent their condition deteriorating to the stage where they were beyond repair.



THE SOLUTION



The surfaces were first of all grit blasted to remove all rust and poorly adhered coatings.

The entire surface was then coated with one coat of Corro-Tech GP, followed by one coat of Chemi-Tech EP which gives excellent protection in this type of working environment.